

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER  
WASH  
39-NACH.V  
2C-

Tieton Dam, Spillway and Drum Gates  
South and East of State Highway 12  
Naches Vicinity  
Yakima County  
Washington

HAER NO. WA-20-C

J. Thomas Wilson, Photographer, October-November 1992

- WA-20-C-1 UPPER SEGMENT OF SPILLWAY CHANNEL, DRUM GATES  
ALONG SIDE OF CHANNEL, LOOKING SOUTH (up the  
channel)
- WA-20-C-2 UPPER SEGMENT OF SPILLWAY CHANNEL, LOOKING SOUTH  
(lined and unlined)
- WA-20-C-3 UPSTREAM SIDE OF SPILLWAY DRUM GATES, LOOKING  
SOUTHWEST (bridge across piers added in 1989)
- WA-20-C-4 SPILLWAY DRUM GATES AND CHANNEL, LOOKING  
NORTHEAST (upstream face and Control House in  
background)
- WA-20-C-5 STILLING BASIN FOR VALVE HOUSE AND ROOF OF VALVE  
HOUSE IN PHOTO CENTER, SPILLWAY CHANNEL (lined  
and unlined at left of photo), LOOKING NORTHEAST
- WA-20-C-6 SPILLWAY CHANNEL, LOOKING NORTH (end of lined  
section)
- WA-20-C-7 GATE OPERATING MECHANISM FOR SPILLWAY DRUMGATE,  
MOUNTED ON PIER